

PowerSpout LH Case Study



Installation at

Kearoa Marae

In association with

Te Runanga o Ngati Kea Ngati Tuara





EcoInnovation is very grateful to **Te Runanga o Ngati Kea Ngati Tuara** for their vision and input throughout the project, and for allowing project details to be shared in this case study. However, this case study does not necessarily reflect the views of the iwi which can be contacted at

Te Runanga O Ngati Kea Ngati Tuara Trust

- ST: 28 Tarewa Road, Rotorua 3010
- PO: P.O Box 716, Rotorua 3040
- **P:** (07) 343 71 53
- M: (027) 5437 153
- E: nkntadm1n@xtra.co.nz

PowerSpoutContact details

Web: <u>www.powerspout.com</u>

PowerSpout is a product proudly designed and manufactured by: Ecolnnovation Ltd 671 Kent Road New Plymouth R.D.1 New Zealand 4371 Web: www.ecoinnovation.co.nz

If you need to contact Ecolnnovation by phone then email first via our web site first and check the local time in NZ if calling from overseas.

Notice of Trademark

PowerSpout – is a USA registered Trademark

Notice of Company Registration

EcoInnovation – is a NZ Registered Limited Company

Project co-ordination and Case Study compilation by Justin Ford-Robertson Ford-Robertson Initiatives Ltd Rotorua justinfr@clear.net.nz

Section 7.3 onwards completed by: Michael Lawley EcoInnovation Limited New Plymouth michael@ecoinnovation.co.nz

Disclaimer

UNLESS SPECIFICALLY AGREED TO IN WRITING, ECOINNOVATION LIMITED:

(a) MAKES NO WARRANTY AS TO THE ACCURACY, SUFFICIENCY OR SUITABILITY OF ANY TECHNICAL OROTHER INFORMATION PROVIDED IN ITS MANUAL OR OTHER DOCUMENTATION.

(b) ASSUMES NO RESPONSIBILITY OR LIABILITY FOR LOSS OR DAMAGE, WHETHER DIRECT, INDIRECT, CONSEQUENTIAL OR INCIDENTAL, WHICH MIGHT ARISE OUT OF THE USE OF SUCHINFORMATION. THE USE OF ANY SUCH INFORMATION WILL BE ENTIRELY AT THE USER'S RISK.

CONTENTS

| 1. | Background 1.1. Outcomes and Benefits | |
|----|---|--|
| 2. | Site Description | 2 2 |
| 3. | Proposed Site 3.1. Turbines and water return | |
| 4. | 4.1. Headstock | 6 7 7 |
| 5. | Resource consent | 9 9 10 10 10 |
| 6. | Implementation 6.1. Digging the channel for the pipe 6.2. Installing the intake 6.3. Constructing the headstock 6.4. Clearing obstructions in the river 6.5. Site restoration 6.6. Installing the turbines – initial trial and testing 6.7. Installing the turbines – final install and commissioning tests 6.8. Installed Performance 6.9. Diversion Pipe Performance 6.10. Flow measurement by NIWA | 11 12 13 14 15 15 18 21 22 |
| 7. | Power connections 7.1. Export power: pricing and process 7.2. Power Lines company: access to distribution network 7.3. Unison consent to connect 7.4. Compliance 7.5. Metering 7.6. Certificate of compliance (COC) 7.7. System maintenance | 23 24 25 26 26 27 |
| | gure 1. Aerial view of the site: marae and hydro | |
| Fi | gure 2. Normal water flow at the top of the waterfall gure 3. Flood waters at the top of the waterfall gure 4. Proposed lay out | 3 |
| Fi | gure 5. Proposed long section gure 6. Rock overhang and fall to river floor beside main river channel | 4 |

1. Background

Te Runanga o Ngati Kea Ngati Tuara investigated the feasibility of generating power from the Pokaitu Stream which borders the Kearoa Marae on Apirana Road, Horohoro. It was part of efforts to help clean up the Waikato River, in partnership with Te Arawa River Iwi Trust (TARIT), other river iwi, landowners and the Waikato Regional Council (WRC). Ngati Kea Ngati Tuara are one of three Te Arawa River Iwi that make up Te Arawa River Iwi Trust and the trust has specific legislation regarding the co-management and co-governance of the restoration of the Waikato river. As such projects that build Iwi capacity to be involved in the restoration of the river, including sustainable use of the resource, are a focus of the trust. It is within this kaupapa that the microhydro project fits.

In 2012, a feasibility study identified that the flows and fall of the Pokaitu Stream was suitable for a micro-hydro to generate power at Kearoa Marae. In addition to reducing the net import of electricity for use at the marae and associated buildings, it was intended to provide a demonstration of possibilities to iwi members, local farmers and the wider collaborative network of the potential for micro-hydro technology to be more widely utilised in rural New Zealand. Having a power source independent of the electricity grid has additional merit as a civil defence resource where the marae could function as local emergency accommodation and local co-ordination hub. It is important to note that the genesis of this idea was formed at a renewable energy hui held at Kearoa Marae in 2011 and historically the site was used to power a waterwheel for a flax mill, at the turn of last century.

1.1. Outcomes and Benefits

Whilst the primary objective is to produce low cost, renewable energy, the proposed rural marae setting offers a number of other opportunities including;

- Potential for the Kearoa marae to act as emergency shelter, particularly if it has its own power generation capability. The potential to establish a local mini-grid will be considered in the future.
- The project aligns well with the National Policy Statement on Renewable Electricity generation 2011 and allied Policies/objectives of regional and local government.
- Regional councils are also likely to encounter increasing interest in renewable energy. The BOP Energy strategy anticipates this and it is likely that this will also occur in Waikato.
- This project could demonstrate potential for micro-hydro in rural areas, and hence be of wide interest to landowners, and rural (farming) organisations.
- This project is funded from the TARIT affiliate environmental fund and is intended to demonstrate environmentally sustainable use of the awa (which is a tributary of the Waikato River). The intention is to show that iwi can utilise the awa as a resource whilst minimising environmental impact.
- Identified during the lwi strategic planning process in 2010 was a desire for the marae to be self-sufficient (environmentally re energy and maara kai, culturally re Te reo and tikanga revitlisation and economically re developing income streams) and this project should enable the marae and associated iwi owned farm to generate as much power as it uses, over a typical year.

Kearoa marae

2. Site Description

The marae is largely surrounded by the Pokaitu Stream. It is a fairly typical rural landscape with predominantly rolling pastures, some forest plantations and riparian trees, and meandering creeks. The Pokaitu Stream has a gentle fall before the 3m waterfall and returns to a gentle fall downstream through the neighbouring pasture. The banks below the waterfall are fairly steep and covered predominantly in gorse and blackberry. The picture shows the marae and the river, with a dotted line indicating the location of the water supply pipe across the corner.



Figure 1. Aerial view of the site: marae and hydro

2.1. Water Flow Rates and Demand


The Waikato Regional Council have supplied historic water flow data taken over successive summer seasons (1986 – 1992) at a point 3km further downstream. This indicates summer flows of 0.7-1.6 cubic metres (700 – 1,600 litres) per second.

Data from the NIWA website (wrenz.niwa.co.nz/webmodel) is summarised as follows:

The NIWA flood data indicated that the stream carries large flood flow volumes, which was confirmed by local residents and on site observations. The proposed design must accommodate flood flows and if necessary the pipe could be closed for protection in flood flows or to reduce water throughput during low summer flows to ensure residual flows over the water fall will be sufficient to support aquatic flora and fauna.

Resource consent was sought for the installation of up to 6 turbines. A flow rate of approximately 50 litres per second is required for each turbine, so the maximum requirement for the system will be 300 litres per second. The head stock was designed to accommodate 6 turbines, but only 3 were installed at the start of the project. If the maximum 300 litres per second is removed, this is approximately 43% of the lower estimate of summer low flow of 700 litres/second, or 26% of low flow average from the WRC data.

| Catchment Area | 31.9 kms ² |
|-----------------------|-----------------------|
| Mean Annual Rainfall | 1640 mm |
| Mean Flow | 897 l/s |
| Annual Flood Flow | 8.7 m³/s |
| 1% AEP (100 yr Flood) | 23.9 m³/s |



3. Proposed Site

The waterfall is approximately 3 metres high. This significant head was selected as the most appropriate location for electricity generation, using the PowerSpout 'Low Head' turbines. Above the waterfall is an undulating area of mown paddock which slops gently down to the proposed turbine site (see pictures below).

The original plan was to build a wooden flume at the top of the waterfall on the marae side of the river. This was considered to be the simplest and cheapest option. However, the flood witnessed during the planning process meant this plan was abandoned since it would have done considerable damage to the proposed installation (see flood pictures below).

Figure 2. Normal water flow at the top of the waterfall





Figure 3. Flood waters at the top of the waterfall

The client did not want to abandon the project, or shift the focus to a solar photovoltaic system: this project was part of a bigger picture about using the water in a sustainable way. A more solid intake and water supply structure would be required.

The option selected was to dig a channel to redirect some of the water flow via a pipe to the turbines, with the intake above the waterfall and the water returned via a few meters below the waterfall. Figure 4 illustrates the original idea for this option.

The intake was located on a bend and perpendicular to the stream flow. This means that the water will enter the pipe at a lower velocity than the general river speed which will reduce impact on fish by enabling them to move away from the pipe intake.



Figure 4. Proposed lay out

Assessments indicated the presence of a rock layer but anecdotal evidence suggests this is relatively soft and should not prove a problem for digging a channel for the pipe(s). Figure 5 shows the water levels and location of bore holes.




Figure 5. Proposed long section

3.1. Turbines and water return

Assessments were also carried out of the riverbank where the turbines were to be sited, and where the water would return via the daft tubes to the river. The rocky overhang was considered to be a very solid base for a headstock structure. There was a shallow pool below separated from the main river by an accumulation of gravel and mud. The bottom of the pool appeared to be hard rock, covered by soft gravel. The hard rock may be sufficient to prevent erosion by the water from the draft tubes.

The pictures below show the assessments underway. It is also clear that the return point is well protected from the main water flow in the river, which should minimise the risk of damage in the event of another large flood.

2.4m

Kearoa marae

LH Case Study



Wooden channel attached to rock here (dependent on supply pipe location/depth)

Figure 6. Rock overhang and fall to river floor beside main river channel

Soft gravel base of shallow pool appears to be 10-20cm deep on solid rock. Could create channel back to river.



Rock face

Soft mud/gravel base

Potential channel through gravel back to awa



Main flow passes to right of a large rock in the awa. Very little currently flowing to the left.



4. Design

The pipe conveys water from the river to the headstock in which the turbines are sited. The water falls vertically in each turbine unit to turn the propeller connected to the generator. Exiting water is conveyed by draft tubes (250mm diameter) back to the river. The foot of the draft tubes is submerged in the retaining structure (if required). The discharge area is below the waterfall and adjacent to the main flow, thus minimising risk of damage from high flows/floods.

4.1. Headstock

It was anticipated that the headstock could be constructed with a concrete pad cast over a sheet of heavy steel reinforcing mesh. A 400mm high block wall would be built on top of this pad, and height finetuned with timber edging. The headstock contains an overflow channel to discharge excess volume.

The structure would overhang the rock, with turbines inserted in a single line parallel to the rock with





Figure 7. Concept designs



centres approximately 500mm apart. This could be cantilevered and/or it may require support from below. The foot of the draft tubes should be attached to something solid (crossbar) which would offer some protection in the event of a flood. It appears that the soft bed of the shallow pool could be removed allowing the water to be discharged onto the rock river bed, but a precast concrete 'trough' anchored to the river bed could minimise erosion risk and provide extra flood protection. It is also possible that the draft tubes will be attached to this concrete structure to further reduce the risk of damage in the event of an extreme flood.

The pipe conveys water to the head race which contains the turbines. Each turbine is connected to a draft tube which carries the water down onto the rock or into a precast concrete trough in the natural pool area below the waterfall and adjacent to the main flow. A precast structure meant there was no need to pour concrete in the stream which would have breached consent conditions.

4.2. Intake structure

It was initially proposed (Figure 8) that the intake would incorporate a concrete 'wingwall' structure in a bend of the river. There is a consent requirement that the intake will be covered by a mesh/grille of no more than 3mm to minimize or avoid impacts on aquatic life. This was met by using a 3mm woven stainless steel mesh tube over the initial1.2 m length of 600mm pipe.

The intake will clog up quickly at 300 l/s so will need a cleaner. The initial proposal was to position a brush (2 x standard brush heads) over the tube, a motor via a belt rotates the tube and scrape off leaves etc. A simple 12 VDC windscreen wiper motor turns on for 1 min in every 10 mins. Power is supplied by a 12 VDC PV panel and small battery or a DC/DC converter off the hydro to keep the battery full.




Figure 8. Initial design for intake

Another consent condition related to the ability to control water flow to ensure minimum residual flows in the river, and there is value in being able to restrict maximum flows to the turbines. These were both achieved through the use of a precast concrete septic tank with holes cut in both ends.

4.3. Refining the design

Figure 9 illustrates the final design incorporating the elements above: precast concrete septic tank for the intake and culvert wing walls for the headstock. The ideal depth of water at the turbine will vary but the design aims to keep this in a 300-500 mm range.




Figure 9. Final engineering design

The intake box addresses a number of issues but concern has been raised about the accumulation of floating debris or sediment in the box. It is anticipated that the manhole in the top of the tank will allow access for a person and/or pump to address such concerns.

4.4. Turbines and Power Output

It was estimated that with an available head of 3 metres, a flow rate of 50 litres per second per turbine should be able to generate 750-800W/turbine. The 3 turbines installed initially were therefore expected to use up to 150 l/s and generate around 2.2 kW. This would generate around 20,000 kWh per year, slightly more than current power consumption, with the excess being sold into the grid.



5. Resource consent

Early contact was made with council representatives to ensure relevant criteria are addressed in the consent application. The consent application can take up to 20 days to process from the time a complete application is submitted.

Subsequent to initial discussions a project description was prepared that covered all aspects of the project design and activities, showing clearly which aspects were anticipated to need resource consent and which do not. It also included statements about some activities that would not occur e.g. no machinery would enter the stream as a result of the proposed works.

5.1. Waikato Regional Council (WRC)

Two consent applications were submitted:

- 1. Take up to 300 litres per second of water from Pokaitu Stream for hydro-electric power generation purposes. This is a non-complying activity (Rule 3.3.4.26)
- 2. To construct and use an intake structure and discharge structure on the Pokaitu Stream for hydro-electric power generation purposes. This is a discretionary activity (Rules 4.2.4.4 & 4.3.4.4)

Other activities include earthworks, use and discharge of water. The project description included an assessment that concluded these activities were authorised under various permitted activity rules, and this was accepted by the council.

In this case both of the initial requirements were met i.e.

- adverse effects of the activity on the environment will be minor
- the proposal is not contrary to the objectives and policies

This means the activity could proceed without the need for public notification.

5.1.1. Consultation

Specific consultation has occurred with local Maori, as they are the applicant for this project, with the Fish and Game Council and the Department of Conservation. The parties' concerns regarding the intake velocity, size of the screen mesh and timing of works have been addressed in the modified proposal which will

- limit the intake velocity to no more than 0.3 m/s,
- limit the screen size to no more than 3 mm and
- restrict construction activities (not to occur between May and September).

5.1.2. Conditions

A range of conditions were included in the resource consents to ensure impacts were avoided or minimised. Some of the major elements were:

- The Waikato Regional Plan requires screen apertures not to exceed 3 mm in diameter and intake velocities not to exceed 0.3 m/s for permitted activities. As both these standards are met, any adverse effect on aquatic species impingement or entrainment arising from the intake screen or velocity is likely to be less than minor.
- The reduced residual flow should not compromise the aquatic values of the stream. The residual flow calculations are based on 5 year low flows, and in this case the residual flow was raised to 150 l/s, and a review included to enable the residual flow to be increased should adverse effects arise.

- All structures that are in, on or over the bed of the stream would be precast or preconstructed so that physical works would not occur over the stream. The consent holder shall take all practicable steps to minimise the disturbance of the stream bed during the construction activities and to minimise the release of sediment.
- Any sections of the stream bank or its adjacent surfaces which are disturbed during construction of the intake or discharge structures shall be immediately stabilised upon completion of works to prevent erosion

5.1.3. National Policy Statement for Renewable Generation, 2011

The installation is consistent with the objective of this NPS i.e. "To recognise the national significance of renewable electricity generation activities by providing for the development, operation, maintenance and upgrading of new and existing renewable electricity generation activities."

5.1.4. National Policy Statement for Freshwater Management 2011

This NPS is primarily concerned with water quality and water quantity. The activity is for a non-consumptive take and thus allowing it would not impact on the overall quantity of water in the stream, apart for the small section (24 metres) of the stream between the take and discharge locations. Hence the installation would not be inconsistent with the requirements of this NPS.

5.1.5. <u>Outcome</u>

Consents were granted for 35 years, with the option to conduct a 5-yearly review to ensure conditions were being met.

Within three months from the date when this resource consent is first exercised, the consent holder is also required provide the Waikato Regional Council with documented evidence from a suitably qualified person that the installation can continuously comply with conditions relating to intake velocity and residual flows. The consent holder shall also provide as-built plans of the structures within 3 months of the completion of this stage of the project.

5.2. Rotorua District Council

RDC first classed the activity as a hydro development like a new power station, but then decided the WRC consent was sufficient.

"The rules in the utilities chapter does refer to power stations requiring consent, however, I do not consider this activity to qualify as a power station. Your application states that consent is required from the regional council and that should cover the issues relating to ecology and water take."

However, they also cautioned that the Proposed District Plan (not yet in effect) does require a consent for small scale hydro power generators.

6. Implementation

Before any work commenced on site, karakia (prayers) were offered by a local kaumatua and Trustee, Manahi Bray.

Following the blessing and armed with resource consents, design drawings and conservable excitement, it was time for the machinery to be brought in. Diggers, sections of pipe, and precast concrete structures appeared and the work began.





6.1. Digging the channel for the pipe



The channel retained a section of river bank in place to avoid flooding the work site.

6.2. Installing the intake

The septic tank was put in for the intake. The hole in the top will allow access for a pump or person. The flow control mechanism will allow the flow to be restricted or cut off entirely.







Once the pipe was laid and the flow control mechanism completed, concrete was used to ensure no water flow around the sides of the tank. Then the channel was refilled and grass laid, covered with straw to reduce the risk of erosion before the grass established.



The pipe was laid in the trench with one end perforated and inserted into the concrete tank. It is shown here before the 3mm mesh screen was inserted.



The intake was surrounded by large rocks to minimise erosion. With the control gate almost closed the water flow and velocity into the pipe is very low.



6.3. Constructing the headstock

The first stage addressed the water return to the river. A trough was laid as planned, but it was discovered that the rock below was very hard. Water could be returned directly onto the rock without erosion issues. This would mean the bottom of the draft tubes would be about 400mm below the river level.

Considerable care was taken to ensure no works affected the river. Note the water still crystal clear i.e. no sediment issues.



The headstock construction included steel girders set in concrete at the end of the channel, attached to support poles in the river bank below. The precast trough (450 mm deep) was laid on the girders such that the top of the trough was 50 mm below the intake water level.

Holes were cut in the base of the trough to accommodate the turbines. All 6 holes were cut and the PowerSpout seals inserted; initially 3 turbines will be inserted and the other holes blocked off.

A section of the trough wall was removed to allow the wingwall to be inserted. This will help to ensure that the water spreads even across the trough.

Once the pipe was connected and the site restored it looked like this.



In the pictures above the intake gate was only partially open. With the intake gate fully open the water rises to a depth of 400mm in the trough. Levels will be tested again once the turbines are inserted.

There is no obvious impact on the river bank, even without the draft tubes in place. There is no sediment in the water returning to the main river flow. The structure is well protected from, and clear of, the main water flow.

6.4. Clearing obstructions in the river

A few large logs stuck in the waterfall, and a willow tree overhanging the river were removed to reduce risk of damage to the draft tubes. The logs could be fairly destructive if dislodged and hit the water return structures. The willow was beginning to obstruct the water flow and could divert water to the other side of the river where the tubines are located.



6.5. Site restoration

Finally the channel was laid for the electrical cables (sufficient for all 6 turbines) from the headstock to the switchboard in the marae. With the major works complete the site was restored to protect soil and river bank. The pictures below show the constructions site mid-works and subsequently restored and awaiting the turbines.



6.6. Installing the turbines – initial trial and testing





The turbines were discussed with the local team. There was considerable enthusiasm for the project and a high level of understanding of objectives and constraints. This also led to discussion of other opportunities in the area.

Kearoa marae



Three turbines were initially installed in the trough. Three 250mm draft pipes were also inserted, attached at the base with clamps.

An electrical breaker box was attached to the wall beside the headstock and connections made to each turbine. The cable tray was kept high to keep the cables well clear of the water.

Once the turbines were in place they were connected to the switchboard in the marae. An import-export meter will be installed to enable surplus power to be put into the main power grid.



It was estimated that each turbine should generate 700-800 W. The 3 turbines installed initially were therefore expected to have a capacity of around 2.2 kW. This would generate around 20,000 kWh per year, slightly more than current power consumption, with the excess being sold into the grid. Output in testing was measured at 2.1kW as shown.

In the initial run there was high velocity (from pipe) flow hitting centre of enclosure and resulting in turbulence which lowered the performance of the turbines.



A 250mm high temporary barrier (shown next was installed to deflect this velocity upwards. This worked well but caused much water mixing



PowerSpout

LH Case Study

The head was initially 2.8m but with a 400mm increase in the trough sides this will be 3.2m. Generation was expected to increase with the additional head and once air/water mixing has been eliminated as air can expand in the draft tube.

With the walls raised testing was done with the temporary baffle removed and restricted water flow to avoid flooding the turbines. Generation was shown to increase to 2.4 kW. With the turbines with extended shafts the water supply can be opened further and generation will increase to over 2.5 kW.



6.7. Installing the turbines – final install and commissioning tests

The pictures above show that the turbine base was positioned too low relative to the pipes, this resulted in a high pipe velocity, turbulence, air mixing and reduced performance. To correct this a timber edging was added to lift the water height so that the supply pipe is almost fully submerged as shown. This correction resulted in the turbines being too low. Hence the height of the turbine generators had to be adjusted to correct this.

Two options were trailed:

- Lifting the existing turbines on a plinth
- Extending the drive shafts

After testing it was evident that a drive shaft 2 x longer than normal had a critical whirling speed close to the turbine operational speed. This resulted in excessive vibrations. The only viable solution was to make a plinth for each turbine to sit on as shown.

This solution of a timber edging and the turbines raised on plinths worked well in solving the relatively small error in the earth works height.

It should be noted that mounting the turbine too low is an error that can be corrected on site for little additional costs, mounting them too high is an error that cannot be corrected. For this reason installers tend to be cautious and install turbines slightly too low, correcting/fine tuning them in the manner shown.



PowerSpout

Kearoa marae

LH Case Study

This picture (3 turbines operating) shows correct operation, note the smooth water surface contrasts sharply with the earlier pictures.

Flooding of the river will result in the water height increasing until water flows over the timber sides falling back into the river below.

In extreme flood events the intake gate can be manually closed to offer good flood protection.





The water velocity in the short diversion race from the main river (to the intake gate) was observed to be higher than expected. Close inspection of the picture shows that some large boulders have fallen into the race restricting the flow to the gate. Once the remaining 3 turbines are installed these boulders will have to be removed and the race made a little wider to accommodate twice the flow shown.

Once these boulders were removed, and the intake screen installed the intake looked like the picture below. Note the greatly reduced surface current which helps reduce the quantity of debris that is drawn toward the intake from the main river flow.





Intake gate can be lowered in high rain events to reduce the risk of system damage from flooding.

6.8. Installed Performance

The EnaSolar 3kW inverter was initially operated in solar mode. Although it tracked to the maximum power point of 2.8kW at 219 VDC, it had a tendency to wander down by up to 500W, likely the result of the solar PV software tracking algorithm not well suited for hydro.


Once the maximum power point has been observed, it is a relatively easy matter to fix any tracking wander issues.

In the case of the Enasolar inverter you can:

- Slow the inverter tracking rates
- Use table mode settings

Table mode settings were entered as per the picture and any tendency for the power output to wander was eliminated.





LH Case Study

It should be noted that if one turbine is removed then the remaining 2 turbines will not optimally work. You can fix this problem by editing the table data so that for a little change in voltage there is 1 turbine change in power output as shown.

| Voltsge (V) | Power (W) | Notes |
|-------------|-----------|-----------|
| 0 | 0 | |
| 100 | 900 | |
| 200 | 950 | 1 turbine |
| 210 | 1900 | 2 turbine |
| 218 | 2800 | 3 turbine |

| Voltage (V) | Power (IV) | |
|--|----------------|--|
| 0: | 0 | |
| 100.0 | 900 | |
| 200 | 950 | |
| 210 | 1900 | |
| 218.0 | 2800 | |
| 0.0 | 0 | |
| 0.0 | 0 | |
| and inc Power (Table and Dec Power (Tab | V. Contraction | |

The other option you have, to obtain stable operation, is to stay in PV mode and adjust the settings:

- MPPT Delay (ms)
- MPPT Voltage Step (%)

Increasing delay time and reducing the step size can also produce a very good result and solve tracking issues.

The measured head at the site (water to water level) was 3.15m. Estimated flow rate was 132 L/s (obtained from previous test results), this resulted in a very respectful water to grid efficiency of about **69%.** Observed generation was 2.8kW, calculated power for a site with 3.15m head was 2.1kW, so the turbines are performing better than expected relative to the PowerSpout LH online calculation tool, which tends to be rather conservative.

6.9. Diversion Pipe Performance

A 600mm ribbed diversion pipes was installed. It had a fall of 100mm over 25m. When flowing at 132 L/s it way observed that the water height was 150mm from the top of the pipe at the intake and 115mm at the turbine end.

So allowing for the 100mm fall on the pipe the water level drops by 65mm, the represents the friction loss in conveying the water to the turbines.

Installing 3 more turbines and increasing the flow to 264 L/s will result in the drop increasing from 65mm to about 150mm. This looks to be in order and checking with the LH calculation tool verifies this to be correct. In general try to keep the flow toward the intake to be under 0.3m/s to reduce the water draw that can pull fish and leaves towards the intake as this will result in more cleaning being required.



If you use corrugate pipe go up 1 pipe size to be on the safe side, it is better to be too big than too small.

6.10. Flow measurement by NIWA

<u>NIWA</u> was engaged to measure the flow to confirm it met consent conditions. The 129 L/s measured by NIWA compares closely with the 132 L/s estimated by EcoInnovation (from previous test data for their turbines at this head).

Doubling the take will allow 6 turbines to operate and still meet consent conditions. With 6 turbines operating the Max velocity of 0.3 m/s may be exceeded. Increasing the flow area and depth around the intake pipe will reduce this.

| PO Box 716 Rotorua 3040. The Te Ruanaga O Ngati Kea Ngatai Tuara Trust operates a small Hydro electric scheme on the Pokaitu stream. The trust engaged Niwa to measure the stream flow into the hydro scheme and the residual flow below the intake structure to meet conditions in Resource consent no 127396. The table below summarises the results of two flow gaugings carried out on the 8 th August 2014. Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second 129 litres/second | | | | | |
|---|---|---|----------------------------------|--|--|
| Rotorua 3040. The Te Ruanaga O Ngati Kea Ngatai Tuara Trust operates a small Hydro electric scheme on the Pokaitu stream. The trust engaged Niwa to measure the stream flow into the hydro scheme and the residual flow below the intake structure to meet conditions in Resource consent no 127396. The table below summarises the results of two flow gaugings carried out on the 8 th August 2014. Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second | Te Ruanaga O Ngati Kea Ngatai Tuara Trust | | | | |
| Flow (litres/second) <300 litres/second 129 litres/second | PO Box 716 | | | | |
| Pokaitu stream. The trust engaged Niwa to measure the stream flow into the hydro scheme and the residual flow below the intake structure to meet conditions in Resource consent no 127396. The table below summarises the results of two flow gaugings carried out on the 8 th August 2014. Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second | Rotorua 3040. | | | | |
| residual flow below the intake structure to meet conditions in Resource consent no 127396. The table below summarises the results of two flow gaugings carried out on the 8 th August 2014. Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second | The Te Ruanaga O Ngati Kea Ngatai Tuara Trust operates a small Hydro electric scheme on the | | | | |
| Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second 129 litres/second | Pokaitu stream. The trust engaged | Niwa to measure the stream f | ow into the hydro scheme and the | | |
| Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second | residual flow below the intake stru | ucture to meet conditions in Re | source consent no 127396. | | |
| Consent condition Intake structure (measured) Flow (litres/second) <300 litres/second | The table halour communations the su | and the of the of the second | ind out on the oth August 2014 | | |
| Flow (litres/second) <300 litres/second 129 litres/second | The table below summarises the results of two flow gaugings carried out on the 8 th August 2014. | | | | |
| | | Consent condition | Intake structure (measured) | | |
| Max velocity (metres/second) <0.3 metres/second 0.22 metres/second | Flow (litres/second) | <300 litres/second | 129 litres/second | | |
| | Max velocity (metres/second) | <0.3 metres/second | 0.22 metres/second | | |
| Average velocity(metres/second) 0.15 metres/second | Average velocity(metres/second) | | 0.15 metres/second | | |
| | | | | | |
| Consent condition Pokaitu stream below intake | | Consent condition | Pokaitu stream below intake | | |
| Flow (litres/second) >150 metres/second 469 litres/second | | >150 metres/second | 469 litres/second | | |
| | Flow (litres/second) | | | | |
| The flow gaugings were carried out with a current meter with a minimum of 20 verticals | | it with a current meter with a m | ninimum of 20 verticals | | |
| | The flow gaugings were carried ou | It with a current meter with a m | ninimum of 20 verticals | | |
| The flow gaugings were carried out with a current meter with a minimum of 20 verticals Yours faithfully | The flow gaugings were carried ou | it with a current meter with a m | ninimum of 20 verticals | | |
| | The flow gaugings were carried ou | it with a current meter with a m | ninimum of 20 verticals | | |
| | The flow gaugings were carried ou Yours faithfully | it with a current meter with a m | ninimum of 20 verticals | | |

7. Power connections

Please note that the following section is based on the situation at the time of writing but the electricity system in NZ is in a state of uncertainty so please check details with your local lines company and power retailer.

7.1. Export power: pricing and process

The current system is designed for 3 turbines, using a 3kW inverter to connect to the grid. This leaves options for expansion ie either a direct link or add another inverter to connect to the grid (and possibly battery bank). The output is designed to meet current consumption without too much surplus, given the lower value of selling power than avoiding power consumption.

Marae power use in the year to May 2011 was nearly 19,000 kWh, with typical monthly use of around 1,000 - 1,500 kWh (range 800 - 3,200). 3 turbines generating 750W each would produce 1,650 kWh per month or nearly 20,000 kWh/yr. (2.8kW of generation as installed = 24528 kWh/year). This data indicates a typical surplus, but this would vary a little between months.

There are two main power companies offering a good return for export power from small distributed generation systems: Meridian Energy and Contact Energy:

- Meridian export energy is based on a stepped plan: 25 cents per kWh (plus GST if registered for GST) for the first 5kWh per day (e.g. 150 kWh for a 30-day billing cycle) and 10 cents per kWh (plus GST if registered) thereafter.
- Contact Energy offer a flat rate of 17.3 cents per kWh providing the installed capacity is below 10 kW; above this I believe it drops to 7 cents per kWh

If the export energy is as anticipated then the higher rate offered by Meridian is most attractive. If power export climbs above 300 kWh per month then the Contact Energy rate begins to look a better deal.

Meridian was chosen in this instance and steps taken to change to them from the current provider, and seek agreement to install the scheme and sell surplus power. Once installed change energy retailer in nor a major undertaking and this remains an option at this site.

7.1.1. Meridian process guide

Meridian (online guidance) requests customers follow these steps in setting up a renewable generation scheme which has a rated capacity of 10 kW or less:

- 1. Select the supplier who stocks the system you wish to install. Make sure that your chosen supplier provides you with certificated evidence that the system you want complies fully with the AS4777 standards, and has also been tested to that standard by an independent test organisation in either New Zealand or Australia.
- 2. Select an electricity specialist to help you, such as an electrician, an electrical engineer or a suitably qualified electrical contractor.
- 3. Contact your local network company to get an application form (for example, Orion or Wellington Electricity Lines). Submit the form and wait for their written response. This can take up to 20 business days.
- 4. Advise us you are installing a turbine or solar panel. You can email us at <u>ssrg@meridian.co.nz</u> or call us on 0800 496 496.
- 5. If you're not a Meridian customer, you'll need to join us so we can give you pricing options. You'll also need to request an upgrade of your meter so it can record import and export electricity flows. As delays in meter upgrades can occur, please advise us as soon as possible when your project gets underway.
- 6. Your electrician needs to advise Meridian whether the supply to the meter-board is single-phase or three-phase in order for us to install the correct meter type.
- 7. Arrange for your chosen supplier to install your turbine or solar panel system.

7.2. Power Lines company: access to distribution network

The local lines company, Unison, also provide information, including application to use their distribution network, at http://www.unison.co.nz/235/

Once the application is submitted, Unison advise within 5 working days whether the application is complete and within 30 working days whether approval to connect is granted. If Unison does not grant approval, a letter outlining why your application was declined will be sent to you and you may remedy these issues and re-apply. An administration charge is payable to Unison for the connection.

Unison require a certificate of compliance from the electrician to certify that the installation meets AS4777.1-2005. This ensures there is no risk to safety and damage does not occur to the Unison network.

Once the generator receives the approval to connect the Distributed Generation, the generator must give Unison notice of their intention to proceed within 10 working days.

7.3. Unison consent to connect

| his form complets with the Electricity Industry Partscentran Code Pa pplication for connection in accordance with Clause 2, Part 1, Sche | |
|--|--|
| | |
| hy approved connection shall be connected and operated in accordan www.unisoes.co.inz and the lants will be negotiated with Unison prior. | ice with the Deson connectors and operation policies available at to connection |
| APPLICANT DETAILS | TECHNICAL DETAILS |
| Hichael Lawley | Mentenary Ecolnnovation Ltd |
| Ecolnnovation | PowerSpout LH Pro (3 units) |
| Aitree 671 Kent Road | Deter lenge 200-500 Deter Current max 4A per unit |
| New Plymouth 04371 | Deputy up to 3 Deputy 3 |
| Dem 06 7522765 | See Derr PV Gartening |
| n/a | Wind Tartow Down Tartow |
| michael@ecoinnovation.co.nz | Mini Hydro V Oter Japane |
| A second s | the of Phases Bingle These [] |
| LECTRICIAN DETAILS | DC Institute Contraction AC Barretoriana AC Aggretoriana |
| Anthony Peters | Bissume interfaction states Applice comply with AD41777 Brd 🕢 Rev |
| Garpen | Dengin of Instatuty/Discoversion |
| Annu | 3 DC rated 600 VDC 6 AMP HRC fuses (1 per turbine) in an IP65 endosure |
| CryPattode | with a 16 amp 550 VDC DC MCB out to the supply cable. At the end of the supply cable another 16 amp DC MCB prior to inverter. |
| 027 2377526 07 333 1606 | 15-20 amp AC breaker on AC output wire of inverter to local sub main. Details of Protection Education |
| P | This in inside the inverter and as is pert of the ASIN2S4777 standard that |
| a.peters@clear.net.nz | this inverter complies with. |
| STALLATION DETAILS | |
| | UNISON OFFICE USE ONLY: |
| 2006025TU-4A5 (Marae) TrustPower (change to Meridian underway | |
| the second secon | Date manhad |
| 25 Apirana Road | Approved The Desitors |
| Hereberg | Patter shimalise repared 🗋 |
| 07 343 7153 | Plane |
| | Den / |
| · | Eget/re |
| | |
| ments are to constant a Destributed Geographic to the Groups testands and one-law that to configure to the all Desser someworker and aperations sharing to | Be given phones a convert and that the Equipartical and the same spectration |
| norther had had an annual day generative and There resumes write services from the | Unison |
| | The Powerlines People |
| Michael Lawley | Date 11 / 11 / 2013 |
| and the second | APPROVAL TO CONNECT |
| man MLA | |
| and the second | |
| and MLD | |
| and MLD | nz 0800 286 476 |
| and MLD | |
| www.unison.co.n | |
| WWW.unison.co.n | |
| WWW.UNISON.CO.N PLEASE RETURN A COPY OF THE COMPLETED | |
| WWW.unison.co.n | |

7.4. Compliance

For such installations NZ law requires equipment used in such installations to comply with a accepted standards.

These include:

- Inverter: AS4777, CE and C-tick compliance
- Turbines: C-tick and CE
- Noark DC Breaker: CE
- Solar Cable used: PV1-F

These documents can normally be located on the suppliers web site.

In addition to these document you should keep on file the Certificate of Compliance (issued by the site electrician) any certificates of Electrical Inspection if/as required.

7.5. Metering

At the time of commissioning the feed-in meter (supplied by a Meridian contractor have not yet been installed).

A warning sign has been placed at both the inverter and the meter board to make it clear that there is generation at this site.

After commissioning the turbines were turned off until the meter and the electrical inspection have been completed.



7.6. Certificate of compliance (COC)

| Compliance ar Electrical Safety Cen This form has been issued by the Electrical Worker | | titera assess | | |
|---|---|------------------|------------|--|
| Unique ID: | Itada iostallations os past lostall | Selety | Competency | |
| Part 2 of AS/NZS 3000 and are safe to be connected to a 230/400 volt multiple earth new | tral (MEN) system of electrical a | supply. | omply with | |
| (1) Location of installation | 1 | | | |
| Address: | | | | |
| (2) Customer Information | | | | |
| Name: KEAROA MARAE | | | | |
| Postal Address: 31 APIRANA Ro | | | | |
| Phone and Email: ROTORVA | | | | |
| (3) Electrical Worker Informat | ion | | | |
| Name: Registration/ | | | | |
| Organisation: Telephone N | | | | |
| Email: | | | | |
| Name of person(s) being supervised: | | | | |
| (4) Work Details | | | | |
| The work is (circle): additions alterations I new work | | | | |
| The prescribed electrical work is: High Risk General Low Risk friess tick (r) as appropriate) | | | | |
| Indicate the number of each item installed or altered: Other Work? | - | | | |
| Installed or altered: Other Work? Number of lighting outlets: <u>CENERATOR SCHEME</u> | Tick (/) if work includes | E | | |
| Number of socket outlets: | <u> </u> | eest to noi | of supply | |
| Number of socket outlets: O MEN switchboard closest to point of Number of ranges: O Main Earthing System | | | | |
| Number of water heaters: | | | | |
| Number of water heaters: O Electric Lines (5) Certification of Work I certify that the completed prescribed electrical work to which this certificate applies, has been done lawfully and safely and the information in the certificate is correct in that the installation, or part of the installation: | | | | |
| | | | | |
| I has an earthing system that is correctly rated | | Electrical | | |
| contains fittings which are safe to connect to a power supply Helies on supplier's Declaration of Conformity (attach or reference) | Polarity (independent earth): | Worker | Inspector | |
| @ relies on manufacturer's instructions (attach or reference') | Insulation resistance: | 994 KQ | TIGA | |
| Ø has been satisfactorily tested in accordance with Electricity (Safety) | Earth continuity: | .54J2 | | |
| Regulations 2010 | Bonding: Other (specify): | 254.2 | - | |
| G is safe to connect | Contra (apecity): | - | | |
| Electronic reference: | , 2/0/114 | | | |
| Electrical Worker's Signature: A Gab | Date: <u>12/9/(4</u> | | | |
| R is imprectical to attach a copy of a particular manufacturar's instructions, or of any certified design or suppli- documents can be found, in a readily accessible format, through electronic means. | r declarations of conformity, provide a ref | erence to where | the | |
| (6) Electrical Safety Certifica | te | | | |
| I certify that the installation, or part of the installation, to which the Electrical S supply and is safe to use | | onnected to | o a power | |
| Name: Allister Marcain Registration | Practising Licence Number: | I 110 | 7 | |
| Signature: | Practising Licence Number: Date <u>/2 - 8 - /4</u> | | / | |
| CUSTOMER COPY – THIS IS AN IMPORTANT DOCUMENT | AND SHOULD BE RETAINED | , | | |
| | | | | |

7.7. System maintenance

Detailed maintenance instructions (where required) are normally included in the user/install manual for each system component.

A general system maintenance guide is outlined as follows.

Prior to a <u>major</u> flood event:

Close the intake gate. Re-open gate once flood water subsides.

After a minor flood event:

Check system operation, clean away flood debris, check for any flood damage and repair as required.

Inverter:

Check for any red lights on the display which might mean:

- Earth fault detected call electrician
- AC power turned off (no AC warning on inverter display)
- DC power turned off or intake gate closed (no DC warning on inverter display)

If the inverter shows no red lights and the generation display shows over 2.5kW, then all is well. We have noticed at this site that the AC in the building has been turned off by accident (in order to save power). Please ensure this does not happen and that building users are advised to leave the power on.

There is no routine maintenance required for the inverter other than keeping the front heatsink clean of dust.

Intake screen:

• Keep clean of debris, check every 1-2 weeks and clean as needed, more cleaning may be needed after floods, high winds and during Autumn.

PowerSpout LH turbines:

- Replace auto grease canister even 12 months refer to manual.
- Check upper and lower bearing every 12 month replace if required
- Clean intake guide vents and propeller

Periodic maintenance (modified from AS/NZS5033:2012):

Every year:

- Clean site as required
- Check safety signs are still in place
- Periodic inspections should be carried out to check wiring integrity, electrical connections, corrosion and mechanical protection of wiring.
- Check hydro mounting structure for any flood damage and repair
- Test operation of switches/breakers

Every 5 year:

• Verify mechanical integrity of conduits and outside breaker enclosures, tightness of connections, water accumulation/build-up, integrity of lid seals, integrity of cable entrance and/or conduit sealing, integrity of clamping devices.